Create SKF Multilog On-line System IMx Transient Groups for Run up and Coast down Data Collection in SKF @ptitude Observer

Introduction

In vibration analysis, we consider a transient as a non-stationary vibration event due to changes in speed, load or process, e.g., run up or coast down events. This document describes how it is possible to analyze these kinds of events with transient groups in SKF @ptitude Observer using an appropriate configuration depending on customer needs. Additionally, the document recommends a software, firmware and hardware combination in order to have the higher performance during a transient measurement that results in better analysis of these types of events.

Compatibility for higher performance during a transient

The configurations recommended in this document will produce high quality data for analysis of transient events (run up, coast down and over-speed) if the recommended software and hardware versions are used (-> table 1).

		Table 1
ltem	Version	
SKF @ptitude Observer Condition Monitoring firmware	9.0.1 lmx-1.1.pkg	
If SKF Multilog IMx-M is used: SKF Multilog IMx-M Protection firmware	2.0 imxm-214.a48	

Note that if earlier versions are used, the amount and quality of the transient data could be lower.



Measurement considerations

In order to configure a transient group, we need to consider the next points to get reliable measurements during the transient event:

- The time used by SKF Multilog IMx to process one vibration point in an FFT is from 0.1 to 1 second per channel, depending on the configuration of each measurement point and other features configured in SKF Multilog IMx, like alarming. The worst case will be around 16 seconds to process 16 channels.
- Check sensor OK status will increase the measurement/process time. Turn off Check sensor OK status when configuring transient groups (-> fig. 1).

MasCon:	0. Card 1	Sensor type:	Displacement [um] –
Number:	1 *	E.U.:	um	
Name:	1 Y Shaft	Trans. angle:	45 [degn	ees]
Enabled:				0
			90	27
				100
Current shunt:	(Has to be activated	l also in hardware)		100
\sim				
Sama Nicita				
Sensitivity Sensitivity:	1000 mV/um	Zero level:	0 mV	
Sensitivity Sensitivity: Calculation	1000 mV/um	Zero level:	0 mV	
Sensitivity Sensitivity: Calculation	1000 mV/um	Zero level:	0 mV	
Sensitivity Sensitivity: Calculation	1000 mV/um	Zero level:	0 mV	Caladata
Sensitivity Sensitivity: Calculation 0 mV	1000 mV/um	Zero level:	0 mV	Calculate
Sensitivity Sensitivity: Calculation 0 mV 0	1000 mV/um	Zero level:	0 mV	Calculate

Fig. 1. Turning off "Check sensor OK status" in SKF Multilog IMx analogue channels – SKF @ptitude Observer.

- It is not recommended to have more than one measurement point per channel, especially for enveloping measurements 1 to 4 or Digital Peak Enveloping (DPE) measurements in an SKF Multilog IMx unit that is intended to measure transients. This requires a higher processing time that will affect the transient group measurement by reducing the amount of transient data stored.
- Phase alarms are not active in transient groups.
- The more measurement points used in a transient group, the more time is required from the SKF Multilog IMx to process the information. Four channels will show a better performance than eight channels or sixteen channels.
- SKF Multilog IMx is always measuring and calculating all configured items for each channel. Then the unit saves the values according to the value configured in the Interval field in the point property's Spectra tab in the "Data storage" section (→ fig. 2).

General Spectra Trend Alam Advanced Diagnoses FFT settings No. of lines: 1600 • Meas. time: 0.04 s Frequency range: 0.40 kHz, 0.2 400 000 cpm • Window: Hanning • Low freq.: 0 Order analysis shaft: CNone> • Order analysis shaft: CNone> • Fype: Same as trend • Type: Same as trend • Splet filter Isabled Ig PtP] Data storage interval: 2 Interval: 2 Hours • (0=Off) Save Spectra - Time waveform - Phase • System log Øk Cancel	🔵 Meas. poin	nt (Company\ENV 4\IMx S c	old\Calibration\)				×
FFT settings No. of lines: frequency range: 0.40 kHz, 0.2 400 000 cpm Resolution: 25 Hz/Line Window: Hanning Low freq.: 0 Low freq.: 0 (None> Active range Type: Same as trend Splice filter Interval: 2 Hours (0=Off) Save Splectra - Time waveform - Phase Qk Cancel	General Sp	pectra Trend Alarm Adv	anced Diagnoses				
No. of lines: 1600 Meas.time: 0.04 s Frequency range: 0.40 kHz, 0.2400 000 cpm Resolution: 25 Hz/Line Window: Hanning Low freq.: 0 [Hz] Average: Frequency Number: Order analysis shaft: Order analysis shaft: Frequency Number: Active range Type: Same as trend Splee filter Image: Image: Image: (0=Off) Save Spectra - Time waveform - Phase System log	FFT setting	gs					
Frequency range: 0.40 kHz, 0.2 400 000 cpm Window: Hanning Low freq: 0 Low freq: 0 Order analysis shaft: Number: Order analysis shaft: Number: Active range • Type: Same as trend Spike filter 0 Image: Image: Image: Image: Image: Image: Type: Same as trend Spike filter 0 Image: Image: Image: Image: Image: Image: Spike filter 0 Image: Image: Image: Image: Image: Image: System log Image: System log Image: Image: I		No. of lines:	1600 👻	Meas. time:	0.04 s		
Window: Hanning Low freq.: 0 I	Mhu	Frequency range:	0 - 40 kHz, 0 - 2 400 000 cpm 🔹	Resolution:	25 Hz/Line		
Low freq.: 0 [H2] Average: Frequency Number: 1 • Order analysis shaft: (None> Active range Type: Same as trend • Type: Same as trend • Spike filter Data storage Iterval: 2 Hours • (0=Off) Save Spectra - Time waveform - Phase • System log Qk Cancel		Window:	Hanning				
Average: Frequency		Low freq.:	0 [Hz]				
Order analysis shaft: Active range Type: Same as trend Type: Same as trend Soke filter Image: Soke filter		Average:	Frequency Number: 1				
Active range Type: Same as trend • Type: Same as trend • Spike filter Data storage Interval: 2 Hours • (0-Off) Save Spectra • Time waveform • Phase • System log Qk Cancel		Order analysis shaft:					
Active range Type: Same as trend • Type: Same as trend • Spike filter Enabled 0 [g PtP] Data storage Interval: 2 Hours • (0-Off) Save Spectra - Time waveform - Phase • System log Qk Cancel		,					
Ivpe: Same as trend Type: Same as trend Spike filter Image Image Image Interval: 2 Base Spectra - Time waveform - Phase System log Ok Cancel	- Active ran	nge					
Type: Same as trend Spice filter Image Interval: 2 Hours (0=Off) Save Spectra - Time waveform - Phase System log Qk		Type: Same as tren					
Spike filter Image Image Image Image Image Save Spectra - Time waveform - Phase System log Ok Cancel		Type: Same as tren	d 🔻				
Enabled 0 [g PtP] Data storage Interval: 2 Interval: 2 Hours Save Spectra - Time waveform - Phase System log Qk	Spike filte	er -					
Data storage Interval: 2 Hours Save Spectra - Time waveform - Phase System log Qk Qancel	0	Enabled	0 [g PtP]				
Interval: 2 Hours (0=Off) Save Spectra - Time waveform - Phase System log Qk Cancel	- Data stora	age					
System log Qk Cancel		Interval:	2 Hours -	(0=Off)			
System log Qk Cancel		Save	Spectra - Time waveform - Phase 💌				
System log Qk Cancel							
System log Qk Qancel	4						
	System lo	QQ				Qk	<u>C</u> ancel

Fig. 2. Measurement point configured to save data every two hours - SKF @ptitude Observer.

- The database size shall not be bigger than 120 GB. If the customer needs more space, they shall use multiple databases and several monitor services that could be installed in the same server (refer to application note CM3205, *Multiple databases and monitor services in SKF @ptitude Observer*).
- Customers shall use **harmonic points** when configuring transient groups in SKF @ptitude Observer. A harmonic point is a special point, designed for turbine monitoring, that does order tracking that presents only the harmonic components of a vibration signal (1X, 2X, 3X and 4X).
- Both the amplitude and phase of the harmonic components are available. Since this measurement does not require calculation of the FFT, it is possible to capture essential information at higher rates of speed change.
- During a transient, it is possible to enable or disable the alarm calculation for the harmonic components (1X, 2X and overall) of a harmonic point (
 → fig. 3). If alarms are needed, it is recommended to enable the overall alarm for maximum performance.

Spectra Trend Alam Advanced Transient Runout compensation nt Alam Intervention Intervention Intervention Intervention 2x.N Enabled Intervention Intervention Intervention Intervention Overall Enabled Intervention Intervention Intervention Intervention	pint (Turbine\General tests\System test\B	ase 5 Harmonic\1VD\)
Aam Ix N Enabled 2x N Enabled Overall Enabled	Spectra Trend Alarm Advanced Trans	sient Runout compensation
Aam 1 x N Enabled 2 x N Enabled Overall Enabled	t	
1 x N Enabled Overall Enabled	Alam	
Overall Enabled	2 x N Enabled	
	Overall Enabled	
a log Qk	log	Qk

Fig. 3. Transient alarm configuration for harmonic points.

Procedure to create a transient group in SKF @ptitude Observer

This procedure shows how to set up a transient group in SKF @ptitude Observer for SKF Multilog IMx devices and what each configured parameter means. During a transient group configuration, remember the previous points mentioned in the *Measurement considerations* section.

1 Go to the **Database** menu and select **Measurement groups**, click **Add**, and then choose "Transient" (→ fig. 4).





2 From the Settings tab, enter a name and choose the SKF Multilog IMx/MasCon and speed channel (→ fig. 5). Transient closure time is the time to remain in the transient after reaching the primary steady state. SKF @ptitude Observer uses this time to make a decision whether a transient is over or not, for example, to decide if two transient events should be glued or should be stored separately. The SKF Multilog IMx unit will start measuring this time after the Transient state time out is over (see the description in point #5). Finally, set the simultaneous measurements.

Transient		×	_
(1) f	configure the control and trigger of the hese settings will override the individe	measurements done both in transient and normal mode. al measurement point settings of all members of this group.	
Settings S	Spectra Trend Speed ranges Hi	story	1
Name and	d comment		
	Name:	Case 1	
	MasCon/IMx unit:	05. Transient test 👻	
	Туре:	Transient	
	Frequency type:	Frequency	
	Transient closure time:	1 Minutes	
Simultane	eous measurements		
	Speed meas.:	Tacho 4 8 12 16 🔹 Trigg.	
	Process meas.:	<none></none>	
	Digital meas.:	<none></none>	
L			1
		Qk Cancel	J
			-

Fig. 5. Name the new transient group.

3 From the **Spectra** tab, set the FFT settings, active range and storage interval for steady state monitoring (\rightarrow fig. 6).

nsient	The sector page	
	Configure here the settings for the spectra for all members of this group. The 'Active range' and 'Data storage' is used for storing in the normal mode. (This is independe settings under the 'Speed ranges' tab) These settings will override the individual measurement point settings of all members of this gro	ent of data taken in transient mode which uses the up.
Settings	S Spectra Trend Speed ranges History	
-FFT settin	No. of loss	
Mhu	No. of lines: 400 V	
	Frequency range: 0 - 1 kHz, 0 - 60 000 cpm	
Active ran	trange	
Δ		
	Type. Same as trend V	
Data stora	storage	
		Ok Cancel

Fig. 6. FFT settings.

It is not recommended to use more than 400 lines. More lines will end up in a longer data collection time between the trend and the FFT values, and this will also vary if the transient is being measured in low or high speed (-> table 2).

			Table 2
Spectrum lines	Time between spectrum (s)*	Time between trend values at low speed (s), about 2 000 CPM	Time between trend values at high speed (s) about 10 000 CPM
400 200 100	10 10 10	1,02 0,89 0,80	0,96 0,64 0,60

*Configured delta storage for this particular example. The SKF Multilog IMx can process spectra more frequently, but this is not necessary because the analysis can be done using the trend packages that include the dynamic components (1X to 4X and Overall).

4 From the **Trend** tab, choose the active range and storage interval for steady state (\rightarrow fig. 7).

ransient	free-series property					X
	Configure here the settings The 'Active range' and 'Da' settings under the 'Speed r These settings will override	for the spectra for all membrased for the spectra for all membrased for storing anges' tab) the individual measurement	ers of this group. in the normal mode. (This is indep point settings of all members of thi	endent of data taken in t s group.	ransient mode which uses th	e
Settings 3	Spectra Trend Speed	ranges History				
Active rar	nge					
	Type: Speed	Condition:	100 2250 [cpm]	Max allowed delta:	20 [cpm]	
	Type: All	•				
Data stor	rage					
	Storage interval:	1 Minutes (0=Off)				
					<u>O</u> k <u>C</u> ance	el 🛛

Fig. 7. Trend settings.

- 5 Go to the **Speed ranges** tab and define the steps according to your needs (→ fig. 8). The reason for this is that the **Mean harm** parameter (number of revolutions) needs different values for different speed ranges in order to have better measurement accuracy at low, intermediate and high speeds. Each step will be defined by:
- Transient state time out: specifies how long the SKF Multilog IMx will remain sending transient state data after moving from a transient state to a normal state (if the state is stopped, the SKF Multilog IMx will stop sending data). When this time is over, the Transient closure time in SKF @ptitude Observer will start.
- **Rpm min** and **Rpm max:** are the values used to start and end the step. A minimum speed of 60 RPM can be configured in the steps for the transient. Lower speeds will show inconsistencies in phase measurements.
- State: defines if the step will be measured during a normal (steady) state or a transient state.
- Delta Trend and Delta FFT: they are configured to make the SKF Multilog IMx unit save trend and FFT measurements during the transient mode, according to the speed increase or decrease in revolutions. The SKF Multilog IMx will take the last stored rotational speed value, then it will see the configured delta values and will store data during speed increasing or decreasing if the delta is exceeded. Delta Trend shall be 1 CPM and Delta FFT shall be zero for maximum data output.

If the user uses delta trend bigger than 1 CPM (for example, 10 CPM), and reduces the spectrum resolution, the data output in low speed may be less (see **table 6** in the *Real example and data obtained* section).

• Mean ham. (number of revolutions): This is the time counted in number of revolutions in which the sampling for the measurement is done. A setup of two revolutions at any speed will work as a minimum requirement; if **Mean harm.** is set to only one revolution measurement time, the trend might have large variations. For example, for oil whirl detection at 0.5X, the **overall value** will be much better if the measurement is based on at least two revolutions.

It is also possible to set the number of revolutions using 0.1 to 1 second as a "minimum" time required to calculate a measurement point by checking the time for the shaft to make one revolution, and this is recommended especially for normal speed (steady state). See the example below.

Knowing that the time for the measurement to be taken and processed needs to be at least 0.1 seconds, it is possible to use this time to calculate the number of revolutions. If the steady state is 2 000 RPM, we need to calculate how many revolutions are needed at 2 000 RPM to get to 0.1 second.

- 2 000 RPM / 60 s = 33.33 rev/s
- 1/33.33 rev/s = 0.03 s/rev

So one revolution will take 0.03 seconds. As the minimum time for the measurement is 0.1 seconds, we need to configure four revolutions to come over that minimum time for this particular speed.

- 0.03 s × 4 = 0.12 s

This calculation could be done using 0.1 to 1 second, depending on if a faster update rate or a smoother and more accurate trend is desired.

An example of the setup using 0.1 s for the **Mean harm.** for a machine that has a run up from 0 to 5 000 RPM and an over-speed maximum of 5 100 RPM is show in **table 3**.

		Table 3
Recommended setup		
Step (RPM)	Mean harm. (#RPM)	
60 - 5 000	2	

• Max time and Max time FFT: it will save data if Delta Trend or Delta FFT have not saved anything in the configured time.

1)	Delta Trend' Max Time is u Delta FFT is u	e minimum determine ised to for ised to de	start range. s how often ce the stora termine the	a trend value shou ge of Trend values FFT storage rate (e	d be stor should ti very # cp	ed and Mean Har ne Delta Trend se m).	m sets the number of s tting is not reached be	haft cycles that fore this time limi	value is based on (av t.	/eraged)."
ettings	Spectra Tre	end Spe	ed ranges	History						
Speed	ranges Transient	state time	out: 6	0 [s]						
	Rpm min		Rpm max.	State		Delta Trend	Mean harm. [No. revolutions]	Max time	Delta FFT	Max.time FFT
	60		5000	Transient	•	1	2	10	2	10
	* 5000		5100	Steady	•	0	10	20	0	20
	5100		69	Transient	-	1	2	10	1	10
	0	•	60	Transient	~	0	3	10	0	10
	0	•	00	Transient	Ŧ	0	1	60	0	60
	0	•	00	Transient	-	0	1	60	0	60
	0	•	00	Transient	T	0	1	60	0	60
	0		09	Transient	Ŧ	0	1	60	0	60
	0	-	60	Transient	~	0	1	60	0	60
	0	•	69	Transient	Ŧ	0	1	60	0	60
	* Prima	iry stea	dy state	for Normal Bu	ffer sto	orage				

Fig. 8. Speed range setup.

- 6 You always need to configure at least one normal state (steady state) in the steps and an over-speed step after it, as shown in fig. 8.
- 7 For over-speed, the number of revolutions could be the same as in the last step before the normal state (two is recommended). During overspeed, it would be good to store measurements faster (by reducing **Delta FFT** and **Delta Trend**) so it can check in detail what it is happening.
- 8 In steady state, it is not needed to store measurements so frequently, so you could increase the storage time (Max time and Max time FFT) if you want to.
- **9** The **History** tab will be empty until the first measurement happens. Click **OK** (\rightarrow **fig. 9**).

Transient					×
Here you can see all transients done for this grou You can also edit, delete and set reference for th	up. he transient.				
Settings Spectra Trend Speed ranges History					
Transient					
from To	Туре	Keep forever	Comment		
2011-08-05 15:35:19 2011-08-05 15:48:05 2011-08-05 15:25:56 2011-08-05 15:28:29 2011-08-05 15:16:31 2011-08-05 15:77:58 2011-08-05 15:04:02 2011-08-05 15:05:37 2011-08-05 14:06:58 2011-08-05 14:08:26	Transient Transient Transient Transient Transient	No No No No			
		Use a	s reference	Edit	Delete
				<u>O</u> k	<u>C</u> ancel

Fig. 9. Historical transients measured.

asurement gro	ıps		
Database:	Company	•	
Measurement gr	oups		
	Name		
CO	💩 IMx T Transient		
	🍪 Transient IMx M		
		Add	Edit Delete
Members			
Name	Location		
Name Speed	Location Company\IMx T\IMx T\Speed\		
Name Speed Acc 1 Har	Location Company\IMx T\IMx T\Speed\ Company\IMx T\IMx T\Acc 1 Har\		
Name Speed Acc 1 Har Acc 3	Location Company\IMx T\IMx T\Speed\ Company\IMx T\IMx T\Acc 1 Har\ Company\IMx T\IMx T\Acc 3\		
Name Speed Acc 1 Har Acc 3	Location Company\IMx T\IMx T\Speed\ Company\IMx T\IMx T\Acc 1 Har\ Company\IMx T\IMx T\Acc 3\		
Name Speed Acc 1 Har Acc 3	Location Company\IMx T\IMx T\Speed\ Company\IMx T\IMx T\Acc 1 Har\ Company\IMx T\IMx T\Acc 3\		
Name Speed Acc 1 Har Acc 3	Location Company\IMx T\IMx T\Speed\ Company\IMx T\IMx T\Acc 1 Har\ Company\IMx T\IMx T\Acc 3\		
Name Speed Acc 1 Har Acc 3	Location Company\IMx T\IMx T\Speed\ Company\IMx T\IMx T\Acc 1 Har\ Company\IMx T\IMx T\Acc 3\		
Name Speed Acc 1 Har Acc 3	Location Company\IMx T\IMx T\Speed\ Company\IMx T\IMx T\Acc 1 Har\ Company\IMx T\IMx T\Acc 3\		Com

10 The new group will be in the list and you can then click **Close** (\rightarrow **fig. 10**).

Fig. 10. Measurement groups window.

11 Then in the harmonic measurement point that you want to include in the transient group, choose the transient group (\rightarrow fig. 11).

ieneral	Spectra Trend Alarm Adv	anced Transient Diagnoses	
Name an	nd comment		
1	Name:	Acc 1 Har 👻	Enabled
V	Description:		
	Point type:	Harmonic	
Unit and	channel configuration		
	MasCon/IMx unit:	02. IMx T 🔹	[°]
IMX	No. channels:	1	90 270
	Channel X:	001. Acc 1 👻	
	Orientation:	1. Horizontal	
	Rotation direction:	Clockwise 💌	
Simultan	eous measurements		
- Simultan	eous measurements Measurement group:	IMx T Transient 🔹	
Simultan	eous measurements Measurement group: Speed meas.:	IMx T Transient ▼ Speed ▼	
- Simultan	eous measurements Measurement group: Speed meas.: Process meas.:	IMx T Transient Speed	
Simultan	eous measurements Measurement group: Speed meas.: Process meas.: Digital meas.:	IMx T Transient Speed	
Simultan	eous measurements Measurement group: Speed meas.: Process meas.: Digital meas.:	IMx T Transient ▼ Speed ▼ <none> ▼ <none> ▼</none></none>	

Fig. 11. Measurement point's General tab.

12 When the transients occur, measurements will generate for start up and coast down (\rightarrow fig. 12).







Fig. 13. Indication of a runup started.

13 In order to see the transient measurements at any plot (history, trend, bode, 3D, polar), it is needed to select the transient event from the transient buffer. To do this, with the plot open, click the buffer button, select the "Transient" option in the Buffer area and then click the Transient button. In the new window, select the measurement group and transient event, and then click OK (→ fig. 14).



Fig. 14. Select the transient event from the transient buffer.

- **14** If needed, live plots (trends, bode plots, FFTs) can be reviewed during the transient event with an update rate of 1 s for static data (process values like temperature, pressure, etc.), 2 s for dynamic components (1X to 4X and overall) and 3 s for dynamic FFT data.
- **15** If needed, with SKF Multilog On-line System IMx-M it is possible to include virtual measurement points in the transient group. As explained in application note **CM 3162**, *Read Values from Protection Part in Condition Monitoring Part Via Internal Communication with SKF @ptitude Observer*, these measurements come from protection part and their alarm status will also be updated during the transient event.

Real example and data obtained

In this example, we consider a typical system with the next scenario for a multiple transient event (\rightarrow table 4).

- Eight critical machines configured for transient
- Two concurrent machines in transient state
- Twelve semi-critical machines configured for steady state, including alarm spectrum collection

It is assumed that the steady state measurements are evenly spread over time:

- 202 total FFT points stored every 10 minutes (0,34 FFT/s)
- 108 total single value points (0,31 trend packages/s)
- Normal data is one FFT and one trend package every 3 s

Example of typical system

Machine description	Radial	Axial	Seismic	Key	RTD Temp	Transient	Rundown (sec)	Runup (sec)	Full scale (orders)	Full scale (Hz)	Max speed 1 (RPM)	Stop speed 1 (RPM)	Max speed 2 (RPM)	Stop speed 2 (RPM)
ATM Comp ATM Comp ATM Comp HP Comp HP Comp Propane Comp ATM Cond Pump ATM Cond Pump ATM Cond Pump Cond Transfer Pump Cond Transfer Pump Cond Transfer Pump ATM Cond Pump	$\begin{array}{c} 8\\ 8\\ 8\\ 32\\ 32\\ 32\\ 16\\ 16\\ 6\\ 6\\ 6\\ 6\\ 6\\ 6\\ 6\\ 6\\ 6\\ 6\\ 6\\ 6\\ 6$	2 2 2 2 8 8 8 8 4 4 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 2 8 8 8 4 4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	1114442211111111111111111111	5 5 224 222 12 5 5 5 5 5 5 5 5	Yes Yes Yes Yes Yes No No No No No No No No No No No No No	120 120 420 420 300 300	120 120 300 300 240 240	$\begin{array}{c} 12.5\\$	1000 1000 1000 1000 1000 1000 1000 100	7600 7600 12300 12300 12300 9800 9800	300 300 300 300 300 300 300	3000 3000 3000 3000 3000	300 300 300 300 300

Table 5 shows a likely distribution of the transient and steady states for the group of machines.



For the most critical case where (according to **table 1**) two machines are in transient mode and the other 12 machines are in steady state, an SKF Multilog On-line System IMx-M will respond to the multiple transient event as shown in **table 6** if the configuration shown in **fig. 15** is used.

Table 4

J ranges											
	Transient state timeout:		out:	60	[s]						
	Rpm min		Rpm ma	ax.	State	Delta Trend	Mean harm.	Max time	Delta FFT	Max. time FFT	
	[cpm]		[cpm]			[cpm]	[No. revolutions]	[s]	[cpm]	[s]	
	90] -	12300		Transient 🔹	10	2	60	400	60	
*	12300] -	15000		Steady 🔹	300	10	60	300	60	
	15000] -			Transient 🔹	10	2	60	50	60	

Fig. 15. Step setup for the two concurrent transient groups.

Spee

					Table 6
Delta trend	Spectrum lines	Time between spectrum (s)	Time between trend packages (s), low speed. About 2 000 CPM	Time between trend packages (s), high speed. About 10 000 CPM	Time between trend packages over 4 minutes transient. About 2 000 to 10 000 CPM. Seconds/Values (s)
10 10 10* 1*	400 200 100 100	10 10 10 10	1,02 0,89 1,02 0,80	0,96 0,64 0,75 0,60	240/193 = 1,24 239/272 = 0,88 238/185 = 1,29 N/A

*Due to the speed delta change in combination with a low resolution (100 lines), the SKF Multilog IMx will be forced to skip measurements, and this will end up in a longer time between trend packages. If the maximum performance is desired, a **delta trend** of 1 CPM shall be used.

Please contact:

SKF Condition Monitoring Center – Luleå Aurorum 30 · SE-977 75 Luleå · Sweden Tel: +46 (0)31 337 1000 · Fax: +46 (0)920 134 40

Web: www.skf.com

 \circledast SKF, @PTITUDE and MULTILOG are registered trademarks of the SKF Group.

All other trademarks are the property of their respective owners.

© SKF Group 2013

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless prior written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.