`

Knowledge Base Article

Product Group: Software
**Product:** CMSW7302 - @ptitude Analyst Work Notification
**Version:** MA/@A 3.1 or higher / MARLIN 4.1 or higher / Microlog Inspector 1.1 or higher

Abstract

When installing and configuring the Work Notification add-on in SKF @ptitude Analyst, understanding the workflow process is important. The flow chart provided in this article illustrates the work notification cycle, which can serve as a basic troubleshooting tool.

Overview

The following flow chart [Figure 1] shows the Work Notification add-on life cycle:

SKF Reliability Systems
5271 Viewridge Court * San Diego, California, 92123 USA
Telephone 1-800-523-7514 Web: www.skf.com

3222 Rev A
Page 1 of 2

Figure 1. @ptitude Inspector or Analyst & Microlog Inspector or MARLIN
Work Notification processing and status changes

For further assistance, please contact the Technical Support Group by phone at
1-800-523-7514 option 8, or by email at TSG-Americas@skf.com.

SKF Reliability Systems
5271 Viewridge Court * San Diego, California, 92123 USA
Telephone 1-800-523-7514 Web: www.skf.com

3222 Rev A
Page 2 of 2