

## Knowledge Base Article

Product Group: Inspection Systems Product: CMDM6700 – Microlog Inspector; CMVL3600 - MCD Version: OS v1.60.22.0066

## Abstract

This article contains a RFID patch and installation instructions that fixes the SKF Microlog Inspector CMDM6700 with built-in RFID, so that it works with the CMVL3600 MCD and the cable and snap-on adapter. The possibility of someone using the CMDM6700 with the MCD and cable is EXTREMELY low, but it is available if someone needs it.

## Overview

Follow the instructions below to download and install the RFID patch onto a CMDM6700 handheld.

 Save the file "SR14062500\_RFID\_Cx70WM65\_ALL.CAB" located in the Attachments section to the right of this article onto your desktop. [Figure 1] If this article is not being viewed from within the SKF Technical Support Self-Help Portal, please contact TSG for a copy of the attachment.



SKF Reliability Systems 5271 Viewridge Court \* San Diego, California, 92123 USA Telephone 1-800-523-7514 Web: www.skf.com 3733 Rev A Page 1 of 5



Jecu Jecu	Inty Details Previous versions
	SR14062500_RFID_Cx70WM65_ALL.CAB
Type of file:	Cabinet File (.CAB)
Opens with:	🥞 Windows Explorer Change
Location:	C:\Users\mg3212\Desktop
Size:	43.6 KB (44,665 bytes)
Size on disk:	44.0 KB (45,056 bytes)
Created:	Today, July 01, 2014, 2 hours ago
Modified:	Today, July 01, 2014, 2 hours ago
Accessed:	Today, July 01, 2014, 2 hours ago
Attributes:	Read-only Hidden Advanced
Security:	This file came from another computer and might be blocked to help protect this computer.



Figure 2. Check the "Read-only" attribute

 Using Windows Mobile Device Center (on Windows 7), copy the file to the device's \Flash File Store\CABFILES directory. [Figure 3]





 On the device, open Windows Explorer by clicking Start > File Explorer. [Figure 4]





- 5. Navigate to \Flash File Store\CABFILES. [Figure 5]



SKF Reliability Systems 5271 Viewridge Court \* San Diego, California, 92123 USA Telephone 1-800-523-7514 Web: www.skf.com

3733 Rev A Page 3 of 5



6. Click on the file "SR14062500\_RFID\_Cx70WM65\_ALL.CAB" to install the patch. [Figure 6]





Figure 6. Click on CAB file to install

7. When prompted, elect to save the file to "Device" location [Figure 7] and then click Install.



Figure 7. Save to "Device" location

SKF Reliability Systems 5271 Viewridge Court \* San Diego, California, 92123 USA Telephone 1-800-523-7514 Web: www.skf.com 3733 Rev A Page 4 of 5



8. The device may reboot itself a couple of times while it installs the patch.

Once the device returns to the main Windows home screen, the device can be used.

----

For further assistance, please contact the Technical Support Group by phone at 1-800-523-7514 option 8, or by e-mail at <u>TSG-CMC@skf.com</u>.