

Knowledge Base Article

Product Group: MARLIN I-Pro

Product: CMSW6600 – Microlog Inspector

Version: N/A

Abstract

SKF Microlog Inspector does not currently have a firmware distribution tool to push firmware upgrades onto companywide devices. Each upgrade must be handled on an individual basis. This can be a little cumbersome when there are several devices to upgrade. This article names a third party application as one that might work to accomplish this.

Overview

A third party application that some IT folks use to deploy such firmware upgrades onto handheld devices on a large scale is called [SOTI MobiControl](#).

This is a third party application that has not been tested by SKF USA, Inc. SKF USA, Inc. does not provide support for third party applications such as this one.

With applications such as this one, deploying the right firmware files is imperative. The Microlog Inspector files below should be included in the firmware deployment package:

For Windows Mobile 5+ (CMDM 6600, 6700)

- Inspector.CAB
- NETCFv35.wm.armv4i.cab
- sqlce.ppc.wce5.armv4i.CAB

These cab files can be found in the following location:

64-bit system:

C:\Program Files (x86)\SKF\SKF Microlog Inspector Tools\Inspector
Installer\CABs

32-bit system:

C:\Program Files\SKF\SKF Microlog Inspector Tools\Inspector
Installer\CABs

For Windows Mobile 2003 (CMDM 6400)

- Please contact the Technical Support Group at TSG-CMC@skf.com.

For further assistance, please contact the Technical Support Group by phone at 1-800-523-7514 option 8, or by email at TSG-CMC@skf.com.

