



# SKF Compass

## Release notes

Software version 1.1.6

Release date: 2025-July-29

Copyright ©2025 by SKF Group  
All rights reserved

See what's new in Compass Version 1.1.6. New features, enhancements and bug fixes.

## 1. New Features

### 1.1. [Feature 769349](#): IMX-1 sensors dashboard

1.1.1.1. This release introduces a comprehensive dashboard for IMX-1 wireless sensors. The dashboard provides a sortable table view of sensor data including sensor ID, name, health status, battery level, node type, firmware version, and last communication timestamp. It also features a detailed side panel with sensor and gateway information, multilingual support (Portuguese, French, Spanish), and responsive design for smaller screens. The dashboard enhances monitoring and diagnostics by highlighting critical sensor conditions and offering intuitive navigation and filtering capabilities.

### 1.2. [Feature 777166](#): Expected behavior when alarms are automatically removed from source

When an alarm is automatically removed in @O or @A, Compass now clears the corresponding alarm both in the gold layer and in the UI. If the cleared alarm was the only reason for an asset to appear in the Analysis Backlog, the asset is automatically moved to “handled.” If other alarms remain, Compass recalculates and updates the asset’s priority accordingly

## 2. Enhancements

2.1. [746932](#): [Tech Debt] Removed deprecated D&S endpoints

## 3. Bug Fixes

ID	Details
776796	Clicking "Clear" on a Second Applied Filter Also Clears Previously Selected Filter
776282	Extra space before question mark in French confirmation message
776360	Fixed filter icon UI cutoff in Devices & Sensors table
778013	Last Measurement Checkbox Not Fully Visible on Report Generator Page
778015	Corrected header UI misalignment and help icon behavior
778285	Corrected color for “Unsatisfactory” status icon
778583	“Export PDF” button is not visible on small screens in Report Generator

## 4. Known Issues

1. [Bug 778892](#): The SKF label is partially hidden in the header on Site Details page
2. [Bug 778414](#) Tooltip Sticking on Mouseover in Compass Dashboard
3. [Bug 777567](#): IMX-1 Sensor location change (in Observer) is not processed correctly

## 5. Support and Feedback

For any support or feedback, please contact:

- Product Manager: Brian Mitchell, [brian.mitchell@skf.com](mailto:brian.mitchell@skf.com)
- Development Product Owner: Yaara Arbel [yaara.arbel@skf.com](mailto:yaara.arbel@skf.com)